

Appendix E

Long Sea Outfall Photographs -
January 2017



Figure 2017: 1 General view of outfall and WwTW (note construction shaft on the beach)

Figure 2017: 02

Long Sea Outfall viewed from the cliff top. Note that the more orange clay in the foreground appears to be trench backfill. The start of the tunnelled section must be beyond this. Figure 4 in the main report (inset below) must have been taken at a similar location to this but at a lower level.





Figure 2017: 03 Outfall construction tunnel damaged by wave action



Figure 2017: 04 Construction shaft on the beach with exposed tunnel section and WwTW